





Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb /
Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu

XX = AA,AD

- 1 A 963 313 XX
- 2 A 963 054 NU
- 3 A 963 309 NU
- 4 B 960 862 XX
- 6 A 963 314 NU
- 7 A 963 785 NU
- 10 A 963 788 NU
- 11 A 963 324 NU
- 14 A 961 118 NU
- 16 A 962 385 XX
- 17 A 962 708 NU
- 19 A 960 949 NU
- 20 A 963 357 XX
- 21 A 963 404 NU
- 22 A 961 230 XX
- 23 A 960 196 NU




CERAMIX BLUE


A 5655 .. A 5657 ..

0211 / A 866 393
(+ A 865 612)
Made in Germany

	P	bar				Q (3 bar)
	T	°C				l/min
						5



A 5655 ..



A 5657 ..



Ideal Standard
Roentgenstrasse 9
54516 Wittlich
Germany

